

SABRE 426

MODEL YEAR 2008 OPTIONS

ELECTRICAL OPTIONS	Part #
Replace standard batteries with Lifeline AGM	GE0039
Upgrade option GM0041 (*) if AGM batteries chosen	GE0048
Additional AC or DC circuit breaker (specify amperage)	GE0002
CD/FM/AM stereo with four speakers	GE0013
Prewire for stereo and four speakers	GE0014
Flat screen LCD TV and DVD player	GE0051
Hella Cabin Fan with breaker. Specify cabin	GE0004
Additional Hella Cabin Fans (each). Specify cabins	GE0005
Additional 12V outlet (specify location)	GE0003
Xantrex Battery monitor	GE0034
NAVIGATIONAL ELECTRONICS	
Grounding system for SSB radio (must be specified prior to molding)	GE0022
ICOM VHF radio M502 w/antenna and flush mount kit	GE0015
Raymarine ST60001G Autopilot w/controls on cockpit coaming	GE0052
Offset pedestal guard in lieu of standard	GD0011
Angled pedestal guard in lieu of standard	GD0043
MECHANICAL	
Max Prop 3 blade feathering prop (Incl credit for std prop)	GM0032
Additional plate for 12 VDC Sea Frost refrigeration	GM0041 (*)
Seafrost Engine Driven refrigeration	GM0012
Seafrost engine driven refrigeration with 2nd freezer plate	GM0023
Seafrost 110 Volt shore assist	GM0013
Reverse cycle air conditioning 16,000 BTU w/2nd shore cord	GM0014
Additional 7,000 BTU air conditioner	GM0040
4KW gen set installed in sail locker	GE0040
Espar diesel heating system #D5-L	GM0017
FIBERGLASS	
Light Hull color (other than Sabre white)	GH0003
Dark Hull Color	GH0004
Light deck color (other than Sabre white)	GD0001
Contrasting anti-skid color (side deck, coach roof, cockpit)	GD0002
KEEL CHOICES	
Shallow draft bulb/wing keel	GH0024
PLUMBING	
Hot and cold transom shower	GM0006
Salt water wash down system	GM0010
Fresh water washdown in forward anchor locker	GM0036
Tank Watch 4 for holding tank	GM0037
Shorewater inlet to pressure water system	GM0018
DECK AND EXTERIOR WOOD	
Lewmar V3 windlass w/rope chain gypsy	GD0005
Pre-wire for 12 volt windlass	GD0006
Cockpit Cushions - Tan. <u>Side seats only</u>	GD0017
Laid teak cockpit coamings	GD0034
Laid teak on transom step	GD0036
Edson Cockpit table #761 for pedestal guard	GM0003
Teak bang rail on topsides with stainless steel cap	GD0025

RIGGING	
Tapered mast	GR0034
Navtec hydraulic backstay adjuster, split backstay	GR0010
<i>Hall Quick Vang</i> led aft	GR0012
Prep for Inner forestay with running backstays	GR0044
Rod headstay w/turnbuckle	GR0040
Flag halyard to mast head	GR0030
Burgee halyard to spreader	GR0031
SAIL HANDLING	
Harken MK1V roller furling/w deck hardware	GR0005
Prep for furling boom. Delete std boom, vang, reefing lines	
Self tacking jib system	GR0039
Harken adjustable genoa car system	GR0041
Antal HS mainsail slide system with five cars	GD0027
Tides Strong sail track on mast	GD0026
Additional Lewmar sheet stopper (ea)	GD0007
Lewmar Electric Lewmar primary winches in lieu of standard	GD0016
Lewmar Electric main halyard winch in lieu of standard	GD0029
Spinnaker gear with Lewmar winches Harken adjustable genoa cars, Navtec Backstay adjuster, Hall Quik Vang and carbon fiber spinnaker pole	GR0013
Aluminum spinnaker pole on mast. 2:1 controls. Lift aft to stopper	GR0053
MPS/Spinnaker halyard to stopper on mast	GR0049
MPS/Spinnaker halyard led aft to stopper	GR0050
Second genoa halyard led aft to cockpit w/stopper	GR0018
Second genoa halyard on mast w/stopper	GR0051
Spinnaker pole topping lift led aft to stopper	GR0019
Cunningham led aft	GR0042
Harken spinnaker pole track on mast (J+2'), bayonet style 2:1 control	GR0043
DECOR AND INTERIOR WOOD	
Second head unit aft with aft facing chart table	
Ultrasuede fabric main salon only	GH0011
Ultraleather fabric (main cabin only)	GH0036
Corian counter in galley (with Corian sink covers)	GH0012
Accord shades on opening and fixed ports	GH0020

All prices are subject to change without notice and are not contractur

Standard yacht has a Sabre white hull and deck with cherry interior. See individual model specifications and equipment list for complete details. F.O.B. South Casco, Maine.

Sabre sailing yachts are covered by a LIMITED ONE YEAR WARRANTY. This warranty should be thoroughly reviewed by the customer before a purchase agreement is made. Please contact your dealer for details.

Sabre does not guaranty the durability of dark gelcoats. Hulls built with dark colors will fade more quickly than light colors, will show mold imperfections and scratches and can cause the laminate to post cure causing a cosmetic distortion of the surface. These deformations are not structural in nature and therefore are not covered by the Sabre Limited Warranty.